ECS Configuration Chan quest

CCR No. *98-0422*	Logged Date *4/2/98*	Rev. -	Request Type	CCR
Priority Routine ☐	☐ Emergency ☒	Affected Release 2.0	Change Class	INS'

Title (description)
Test SGI network patch on VATC HiPPI hosts

Documents Affected

None

Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or **Tech Reference**
None

RTM Change ☐   **Start New Baseline** ☐

Problem
BDS still does not work. The last problem is an error that occurs when the copy command is issued at the client.

Proposed Solution
Patch 2069 reportedly fixes the problem. Request to install patch 2069 as soon as possible on t1wkg01 and if it works at a later time on, t1drg01, t1spg01 and t1acg01.

NOTE: This patch *does* require a reboot.

Need Date 4/2/98

Impact Analysis:
Organizations Affected:

BOO ☐	Contracts ☐	ECS Chief Eng ☐	FOS ☐	M&O ☒
Procurement ☐	QO ☐	Rel. Dev ☐	Rel. A ☐	Rel. C ☐	SCDO Arch. ☐
Science Off ☐	Security ☐	Subcontrct ☐	Sys. Eng ☒	Sys Verf Acpt ☐

Cost:	None ☒	Small ☐ (Not exceeding $100,000)	Medium ☐ ($100,000 to $500,000)	Large ☐ (Over $500,000)

Schedule: None ☒   Other

Additional LOC _____   Man-Months _____

Materials

Originator Byron V. Peters	*Byron V Peters*	04/02/98
	Signature	Date
Office SED Office Manager	*Randall J Miller*	4/2/98
	Signature	Date

Disposition   Approved ☐   Approved w/Comment ☒   Forward ☐   Disapproved ☐

Comments: MUST Coordinate with RBC & TEST FOR A time.

CCB Chairperson _____   *David L Armst* ___   4/2/98

Signature   Date

CM01OC96

ORIGINAL   *Cm/tt*

ECS